SDP-23-09 – 306 S Main / Scooters – 3rd Submittal review cycle

Review Group / Staff	Comments	Cleare Comme
2. Continue removes 3. LDO 6.2 adjacer genera 4. LDO 6.3 grassed 5. LDO 6.6 a. She app Planning Staff & buil b. Process com c. It all info add 6. FYI - 5 SDP all assoct 7. Buildit façad.	The to Provide a Written response to ALL the comments received; mark-ups to marks-up is OK. The to Cloud/bubble all changes and revisions in plan set, streamlining Staff review; Clouds will be all for Signature set. The to Cloud/bubble all changes and revisions in plan set, streamlining Staff review; Clouds will be all for Signature set. The top Perimeter Bufferyard. A Type 3 25' Landscape buffer is required along the rear property line at the RL zoned property. Applicant is processing a Variance application [VAR-24-02] to modify this ly as shown on this SDP. Outcome of the Variance TBD, there may be further comment. The top Perimeter Bufferyard. A Type 3 25' Landscape buffer is required along the rear property line at the RL zoned property. Applicant is processing a Variance application [VAR-24-02] to modify this ly as shown on this SDP. Outcome of the Variance TBD, there may be further comment. The text and the landscape plan to indicate the ground cover proposed for the areas inside the diagrace to the active open space. On plans, this appears to be light asphalt, but Staff recommends a lareas for active use areas and mulched areas for the landscaping near the menu board & parking area. The site is a photometric plan but appears to be limited to building mounted lights, with no lighting at the roach to the drive-thru area nor for the ADA complaint parking space. Further, there appears to be noting at the menu board and/or the back/employee entrance. Confirm the only lighting is going to be ding mounted, OR revise all plans to show full intent of site lighting / compliance with Section 6.6. The dide Cut-sheets for lighting fixtures; Plans should be revised to show or include all plan requirements in upliance with Section 6.6.F. The discrepancy in the number of fixtures, the location, and the types, should be ressed. The discrepancy in the number of fixtures, the location, and the types, should be ressed. The discrepancy is not reviewed nor approved via this SDP; signage requires unique Sign permits	
Engineering (CJS/B&M) - Brian Laux / Jacque Thompson	See PDF of mark-ups on the Plan set – there are 16 entries/comments. See PDF of Memo comments – there are 13 total comments. See PDF of mark-ups on the Stormwatwer report – there appear to be 5 comments.	

SDP-23-09 – 306 S Main / Scooters – 3rd Submittal review cycle

Wake County Watershed Management - Janet Boyer	No comments were received; previous comment was that Wake County permitting SEC/SWF permits required.	Tbd
COR Public Utilities - Tim Beasley	No further Comments.	✓
Wake County Fire / EMS - Brittany Hocutt	No further Comments.	✓
Parks & Recreation - Eddie Henderson	No further Comments.	✓
NCDOT – Jacob Nicholson	No Further Comments.	✓